

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,098,635 B2
APPLICATION NO. : 10/750585
DATED : August 29, 2006
INVENTOR(S) : Edward A. Burton

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5

Line 49-50, "Counter 204 further outputs the determined proxy frequency for register 210...." should read ---Counter 204 further outputs the determined proxy frequency 218 for register 210....--.

Column 6

Line 23, "...control signal 222..." should read ----control signal 220....--.

Lines 25-26, "...control signal 222..." should read ---control signal 220....--.

Column 7

Line 19, "...system 400..." should read ---the system....--.


Line 37, "...system 400..." should read ---the system....--.

Line 42, "...system 400..." should read ---the system....--.

Line 48, "...system 400..." should read ---the system....--.

Signed and Sealed this

Twenty-third Day of September, 2008



JON W. DUDAS
Director of the United States Patent and Trademark Office